

FIG. 1




FIG. 2





FIG. 3



**FIG. 4**





FIG. 5





**FIG. 6**

FIG. 7









**FIG. 8A****FIG. 8B****FIG. 8C****FIG. 8D****FIG. 8E****FIG. 8F**

FIG. 9A




FIG. 9B




FIG. 9C




FIG. 9D





FIG. 9E



**FIG. 10**




FIG. 11




FIG. 12A




FIG. 12B




FIG. 13




FIG. 14




FIG. 15

TD6230-2796T860

URL <http://www.maintain.co.jp/db/input.html>

TROUBLE DB INPUT WINDOW

OCCURRENCE DATE  4040

TYPE OF APPARATUS  4010

SUBJECT  4030

SERIAL NUMBER S/N  4020

DEGREE OF URGENCY  4050

SYMPTOM  4060

REMEDY  4070

PROGRESS  4080

4100 4110 4120

LINK TO RESULT LIST DATABASE SOFTWARE LIBRARY OPERATING GUIDE

FIG. 16




FIG. 17

